

*Files*


24 June 1957

THRU : Chief, Intelligence Information Staff, ORR  
Chief, Industrial Division, ORR  
Acting Chief, Electrical Equipment Branch, ORR

*Filed  
6/27/57*

Request for Requirements, ORR 11665, JIEM 940-1000-977

25X6A The following requirements are submitted:



a. Size and composition of the labor force.

25X6A

b. Size and composition of plant production (in both value and physical terms, if possible). What percent of the total production of machinery does the plant supply? Is the plant producing at full capacity?

c. Ministerial and other administrative subordination.

d. Origin and condition of the plant equipment -- machine tools, etc.

2. What is source's evaluation of the Plant's technology with respect to the quality of the final products? What is the reject rate in percentage of total output? What are the most common defects in plant's products and what are the probable causes of such defects?

3. Where do the raw materials for the plant come from? What is their quality?

4. To what domestic and foreign consumers are the products of the plant distributed? What percentage of the production is exported? Who is the largest foreign consumer?

5. What shortages exist in either the supply of raw materials or the availability of skilled labor? Be as specific as possible. In addition, discuss any other problems which seemed of major concern to the plant.

25X1A9a



Distribution:

Orig. & 1 - Addressee

1 - D/I

2 - I/EE

25X1A9a

~~CONFIDENTIAL~~